



NEW MEXICO ENERGY, MINERALS  
and  
NATURAL RESOURCES  
DEPARTMENT

OIL CONSERVATION DIVISION  
AZTEC DISTRICT OFFICE  
1000 RIO BRAZOS ROAD  
AZTEC NM 87410  
(505) 334-6178  
FAX: (505) 334-6170  
www.emnrd.state.nm.us/ocd/District 3/district3.htm

**BRADENHEAD TEST REPORT**

(Submit 2 copies to above address)

Date of Test June 8, 2007 Operator CDX RIO, LLC API #30-039- 23698

Property Name Jic. Cont. 148 Well No. 33 Location: Unit H Section 15 Township 25N Range 5W

Well Status (Shut-In or Producing) Tubing 79 Intermediate      Casing 95 Bradenhead 2 #

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

TIME	PRESSURES:		
	BRADENHEAD	INTERMEDIATE	CASING
5 minutes	<u>0</u>		<u>95</u>
10 minutes	<u>0</u>		<u>95</u>
15 minutes	<u>0</u>		<u>95</u>
20 minutes			
25 minutes			
30 minutes			

	BRADENHEAD FLOWED	INTERMEDIATE FLOWED
Steady Flow		
Surges		
Down to Nothing	<u>X</u>	
Nothing		
Gas		
Gas & Water		
Water		

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR      FRESH      SALTY      SULFUR      BLACK     

5 MINUTE SHUT-IN BRADENHEAD 0 INTERMEDIATE     

REMARKS:

Bradenhead had no pressure after 15 minute bleed  
and no vapor.

By W. L.

Witness NONE

Field Technician

(Position)

E-mail address     

