



NEW MEXICO ENERGY, MINERALS  
and  
NATURAL RESOURCES  
DEPARTMENT

OIL CONSERVATION DIVISION  
AZTEC DISTRICT OFFICE  
1000 RIO BRAZOS ROAD  
AZTEC NM 87410  
(505) 334-6178  
FAX: (505) 334-6170  
[www.emnrd.state.nm.us/ocd/District 3/district3.htm](http://www.emnrd.state.nm.us/ocd/District%203/district3.htm)

**BRADENHEAD TEST REPORT**

(Submit 2 copies to above address)

Date of Test 6-7-07 Operator CDX RIO, LLC API #30-039-06153

Property Name Jico Cont. 146 Well No. 12 Location: Unit K Section 4 Township 25N Range 5W

Well Status (Shut-In or Producing) Tubing 98 Intermediate — Casing 98 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

TIME	PRESSURES:			BRADENHEAD FLOWED	INTERMEDIATE FLOWED
	BRADENHEAD	INTERMEDIATE	CASING		
5 minutes	<u>0</u>		<u>98</u>	Steady Flow	
10 minutes	<u>0</u>		<u>98</u>	Surges	
15 minutes	<u>0</u>		<u>98</u>	Down to Nothing	
20 minutes				Nothing <u>✓</u>	
25 minutes				Gas	
30 minutes				Gas & Water	
				Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR — FRESH — SALTY — SULFUR — BLACK —

5 MINUTE SHUT-IN BRADENHEAD 0 INTERMEDIATE —

REMARKS:

\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

By GROVER Vigil  
PUMPER  
(Position)

Witness \_\_\_\_\_

E-mail address \_\_\_\_\_

