



NEW MEXICO ENERGY, MINERALS
and
NATURAL RESOURCES
DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178
FAX: (505) 334-6170

www.emnrd.state.nm.us/ocd/District 3/district3.htm

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test 6/19/07 Operator CDX RIO, LLC API #30-039- 08145

Property Name Jic. #P. C Well No. 2 Location: Unit N Section 14 Township 26 Range 5

Well Status (Shut-In or Producing) Tubing 2 3/4" Intermediate 0 Casing 2 8 1/2" Bradenhead 2 7 1/2"

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

TIME	PRESSURES:			BRADENHEAD FLOWED	INTERMEDIATE FLOWED
	BRADENHEAD	INTERMEDIATE	CASING		
5 minutes	<u>0</u>	<u>0</u>	<u>226^{lb}</u>	Steady Flow	
10 minutes	<u>0</u>	<u>0</u>	<u>220^{lb}</u>	Surges	
15 minutes	<u>0</u>	<u>0</u>	<u>220^{lb}</u>	Down to Nothing <u>X</u>	
20 minutes	<u>0</u>	<u>0</u>	<u>220^{lb}</u>	Nothing	<u>X</u>
25 minutes	<u>0</u>	<u>0</u>	<u>220^{lb}</u>	Gas	
30 minutes	<u>0</u>	<u>0</u>	<u>220^{lb}</u>	Gas & Water	
				Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN BRADENHEAD 0 INTERMEDIATE 0

REMARKS: Braden head had pressure ready @ 226#, blew down
to 0 in 7 minutes
Intermediate, show no pressure ready.

By Roy Jamison

Witness _____

(Position)

E-mail address _____

