

## NEW MEXICO ENERGY, MINERALS and NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178
FAX: (505) 334-6170
www.emnrd.state.nm.us/ocd/District 3/district3.htm

## **BRADENHEAD TEST REPORT**

(Submit 2 copies to above address)

Date of Test 6-7-07	perator_0	CDX RIO, LLC_API #30-039- <b>202</b>	12
Property Name JIC. Con 7:146 Well	No. 26	Location: Unit A Section 4 Town	ship <b>25</b> WRange_5W
Well Status (Shut-In or Producing) Tub	ing <b>4/</b> ]	Intermediate Casing 41 Brader	nhead <u>Ø</u>
OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH			
PRESSURES: TIME BRADENHEAD INTERMEDIATE	CASING	BRADENHEAD FLOWED	INTERMEDIATE FLOWED
5 minutes 0:	40	Steady Flow	
10 minutes	40	Surges	
15 minutes O	40	Down to Nothing	
20 minutes	,	Nothing V	
25 minutes		Gas	
30 minutes		Gas & Water	22425262
		Water	
If bradenhead flowed water, check all of the descriptions that apply below:			(S) RECEIVED S
CLEAR FRESH SALT	ΓΥ	SULFUR BLACK	OIL CONS. DIV. DISE 3
Water			
REMARKS:		INTERVIEDIATE	971101685
By Gloven Vigil  Pumper  (Position)		Witness	· · · · · · · · · · · · · · · · · · ·
(Position)			
E-mail address			