



NEW MEXICO ENERGY, MINERALS
and
NATURAL RESOURCES
DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178
FAX: (505) 334-6170
www.emnrd.state.nm.us/ocd/District 3/district3.htm

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test 6/12/07 Operator CDX RIO, LLC API #30-039- 2664
Property Name Sucilla 151 Well No. 5 Location: Unit K Section 9 Township 26 Range 5
Well Status (Shut-In or Producing) Tubing 145[#] Intermediate Ø Casing 182 Bradenhead Ø

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

TIME	PRESSURES:			BRADENHEAD FLOWED	INTERMEDIATE FLOWED
	BRADENHEAD	INTERMEDIATE	CASING		
5 minutes	<u>Ø</u>	<u>Ø</u>	<u>182[#]</u>	Steady Flow	
10 minutes	<u>Ø</u>	<u>Ø</u>	<u>182[#]</u>	Surges	
15 minutes	<u>Ø</u>	<u>Ø</u>	<u>182[#]</u>	Down to Nothing	
20 minutes	<u>END</u>	<u>TEST</u>		Nothing	<u>X</u>
25 minutes				Gas	
30 minutes				Gas & Water	
				Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN BRADENHEAD Ø INTERMEDIATE Ø

REMARKS: no Pressure Perfor in Bradenhead & Intermediate

By Roy Davini Witness
Fritz Tech.
(Position)

E-mail address

