



NEW MEXICO ENERGY, MINERALS
and
NATURAL RESOURCES
DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178
FAX: (505) 334-6170
www.emnrd.state.nm.us/ocd/District 3/district3.htm

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test 6-8-2007 Operator CDX RIO, LLC API #30-039- 22170

Property Name Jicarilla gas com 35 C Well No. 1-E Location: Unit J Section 2 Township 34N Range 5W

Well Status (Shut-In) or Producing) Tubing 98 Intermediate N/A Casing 493 Bradenhead -1#

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

TIME	PRESSURES:			BRADENHEAD FLOWED	INTERMEDIATE FLOWED
	BRADENHEAD	INTERMEDIATE	CASING		
5 minutes	<u>0</u>		<u>493#</u>	Steady Flow	
10 minutes	<u>0</u>		<u>493#</u>	Surges	
15 minutes	<u>0</u>		<u>493#</u>	Down to Nothing <u>X</u>	
20 minutes				Nothing	
25 minutes				Gas	
30 minutes				Gas & Water	
				Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN BRADENHEAD 0 INTERMEDIATE _____

REMARKS: Braden head had Less than 1# and bled down to
nothing after opening 1" valve. No flow afterward, bled for
15 minutes.

By WAC
Field Technician
(Position)

Witness NONE

E-mail address _____

