

## NEW MEXICO ENERGY, MINERALS and NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION AZTEC DISTRICT OFFICE 1000 RIO BRAZOS ROAD AZTEC NM 87410 (505) 334-6178

FAX: (505) 334-6170 www.emnrd.state.nm.us/ocd/District 3/district3.htm

## **BRADENHEAD TEST REPORT**

(Submit 2 copies to above address)

Date of Test_	6-12	-07 (	Operator_C	CDX RIO, LLC_API	#30-039	2234	75	
Property Nam	е <i>Біс. С</i>	<i>ا</i> مِينَ. 155 Well	No. <u>19E</u>	Location: Unit <u></u> S	Section 29	_Townsh	ip <i>26</i> 1/Range_ <i>51</i> 4	J
Well Status (S	Shut-In or	Producing Tub	ing <i>/05</i> I	ntermediate Cas	ing <i>108</i>	Bradenhe	ead	
OPEN BRA	DENHEAD	AND INTERME	DIATE TO	ATMOSPHERE INDIV	VIDUALLY	FOR 15	MINUTES EACH	_
TIME BRA		PRESSURES: INTERMEDIATE	CASING		BRADEN FLOWEI		INTERMEDIATE FLOWED	3 _
5 minutes	0		103	Steady Flow				_
10 minutes	0		98	Surges				_
15 minutes	0		95	_ Down to Nothin				_
20 minutes		-		Nothing	V .			_
25 minutes				Gas			232425262>2	
30 minutes	· ·			Gas & Water		85	RECEIVED 30	/
				Water		1381	1344111 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	
<u>If bradenhead f</u>	lowed water	, check all of the de	escriptions t	hat apply below:		Paret.	IL CONS. DIV. DIST. 3	/
CLEAR	FF	RESH SAL	TY	SULFUR BLACE	ζ	100	IL CONS. DIA. DIST 3	
5 MINUTE SHU	U <b>T-IN</b> BI	RADENHEAD	<b>)</b>	INTERMEDIATE				
REMARKS:								
								_
						·		-
		r					······	_
	/							_
By 15/120067	- V151			Witness				-
(Positio	n)			_				
E-mail address								