



NEW MEXICO ENERGY, MINERALS  
and  
NATURAL RESOURCES  
DEPARTMENT

OIL CONSERVATION DIVISION  
AZTEC DISTRICT OFFICE  
1000 RIO BRAZOS ROAD  
AZTEC NM 87410  
(505) 334-6178  
FAX: (505) 334-6170  
www.emnrd.state.nm.us/ocd/District 3/district3.htm

# BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test 6/7/07 Operator CDX RIO, LLC API #30-039- 23162  
Property Name Jic - 151 Well No. 812 Location: Unit F Section 3 Township 26 Range 5  
Well Status (Shut-In or Producing) Tubing 95 Intermediate 105 Casing 224 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

TIME	PRESSURES:			BRADENHEAD FLOWED	INTERMEDIATE FLOWED
	BRADENHEAD	INTERMEDIATE	CASING		
5 minutes	<u>0</u>	<u>6 #</u>	<u>224 #</u>	Steady Flow	<u>X</u> <u>Vapor present</u>
10 minutes	<u>0</u>	<u>- 1 oz</u>	<u>224 #</u>	Surges	
15 minutes	<u>0</u>	<u>- 1/2 oz vapor</u>	<u>224 #</u>	Down to Nothing	<u>X</u>
20 minutes	<u>0</u>	<u>0 - Vapor</u>	<u>224 #</u>	Nothing	<u>X</u>
25 minutes	<u>0</u>	<u>0 - Vapor</u>	<u>226 #</u>	Gas	<u>X</u>
30 minutes	<u>0</u>	<u>0 - Vapor</u>	<u>226 #</u>	Gas & Water	
				Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR \_\_\_\_\_ FRESH \_\_\_\_\_ SALTY \_\_\_\_\_ SULFUR \_\_\_\_\_ BLACK \_\_\_\_\_

5 MINUTE SHUT-IN BRADENHEAD 0 INTERMEDIATE 1 #

REMARKS: Intermediate - Blew down fr. 105# to 6# - in 5 minutes  
Continued to vapor after 30 minute Test  
No pressure in Bradenhead.

By Reg Dawson Witness \_\_\_\_\_  
Field Tech.  
(Position)

E-mail address \_\_\_\_\_

