



NEW MEXICO ENERGY, MINERALS
and
NATURAL RESOURCES
DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178
FAX: (505) 334-6170
www.emnrd.state.nm.us/ocd/District 3/district3.htm

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test June 08, 2007 Operator CDX RIO, LLC API #30-039- 23782

Property Name Jic AP TRIBAL 35 Well No. #07 Location: Unit H Section 2 Township 24N Range 5W

Well Status (Shut-In or Producing) Tubing 35[#] Intermediate NA Casing 67[#] Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

TIME	PRESSURES:			BRADENHEAD FLOWED	INTERMEDIATE FLOWED
	BRADENHEAD	INTERMEDIATE	CASING		
5 minutes	<u>0</u>	<u>NA</u>	<u>67</u> [#]	Steady Flow	
10 minutes	<u>0</u>	<u>NA</u>	<u>67</u> [#]	Surges	
15 minutes	<u>0</u>	<u>NA</u>	<u>67</u> [#]	Down to Nothing	
20 minutes				Nothing <u>X</u>	
25 minutes				Gas	
30 minutes				Gas & Water	
				Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN BRADENHEAD 0 INTERMEDIATE _____

REMARKS:

BH had zero. Well starting venting, bringing up
plunger while test is in progress. BH had No action, No Vapor.

By Dobby R. Hatchman
Prod Tech.
(Position)

Witness NONE

E-mail address _____

