



NEW MEXICO ENERGY, MINERALS
and
NATURAL RESOURCES
DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178
FAX: (505) 334-6170
www.emnrd.state.nm.us/ocd/District 3/district3.htm

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test June 12, 2007 Operator CDX RIO, LLC API #30-039- 05942

Property Name Jicarilla Cont. 148 # Well No. 12 Location: Unit A Section 24 Township 25N Range 5W

Well Status (Shut-In or Producing) Tubing 64# Intermediate NA Casing 65# Bradenhead 2#

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

TIME	PRESSURES:			BRADENHEAD	INTERMEDIATE
	BRADENHEAD	INTERMEDIATE	CASING	FLOWED	FLOWED
5 minutes	<u>0</u>	<u>NA</u>	<u>65#</u>	Steady Flow	
10 minutes	<u>0</u>	<u>NA</u>	<u>66#</u>	Surges	
15 minutes	<u>0</u>	<u>NA</u>	<u>66#</u>	Down to Nothing <u>X</u>	
20 minutes				Nothing	
25 minutes				Gas	
30 minutes				Gas & Water	
				Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN BRADENHEAD 0 INTERMEDIATE _____

REMARKS: BH had 2#, bled off to zero in 31 seconds, no
action afterwards.

By Bobby R. Hatchman
Prod. Tech.
(Position)

Witness NONE

E-mail address _____

