



NEW MEXICO ENERGY, MINERALS  
and  
NATURAL RESOURCES  
DEPARTMENT

OIL CONSERVATION DIVISION  
AZTEC DISTRICT OFFICE  
1000 RIO BRAZOS ROAD  
AZTEC NM 87410  
(505) 334-6178  
FAX: (505) 334-6170  
www.emnrd.state.nm.us/ocd/District 3/district3.htm

**BRADENHEAD TEST REPORT**

(Submit 2 copies to above address)

Date of Test 6-4-07 Operator CDX RIO, LLC API #30-039- 22459

Property Name Jacinto Apache 102 Well No 11E' Location: Unit 11 Section 10 Township 26N Range 4W

Well Status (Shut-In or Producing) Tubing 54 Intermediate — Casing 100 Bradenhead 5

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

TIME	PRESSURES:			BRADENHEAD FLOWED	INTERMEDIATE FLOWED
	BRADENHEAD	INTERMEDIATE	CASING		
5 minutes	<u>0</u>		<u>100</u>		
10 minutes	<u>0</u>		<u>100</u>		
15 minutes	<u>0</u>		<u>100</u>		
20 minutes					
25 minutes					
30 minutes					
				Steady Flow	
				Surges	
				Down to Nothing	<u>X</u>
				Nothing	
				Gas	<u>X</u>
				Gas & Water	
				Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR — FRESH — SALTY — SULFUR — BLACK —

5 MINUTE SHUT-IN BRADENHEAD 0 INTERMEDIATE —

REMARKS:

Blew down 3sec

By Leonard Lucero  
Pumper  
(Position)

Witness —

E-mail address —

