



and  
NATURAL RESOURCES  
DEPARTMENT

1000 RIO BRAZOS ROAD  
AZTEC NM 87410  
(505) 334-6178  
FAX: (505) 334-6170  
www.emnrd.state.nm.us/ocd/District 3/district3.htm

## BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test 6-21-2007 Operator CDX RIO, LLC API #30-039- 22524  
Property Name Jicarilla Cont. 148 Well No. 24 Location: Unit D Section 14 Township 25N Range 5W  
Well Status (Shut-In or Producing) Tubing 72<sup>#</sup> Intermediate N/A Casing 68<sup>#</sup> Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

TIME	PRESSURES:			BRADENHEAD	INTERMEDIATE
	BRADENHEAD	INTERMEDIATE	CASING	FLOWED	FLOWED
5 minutes	<u>0</u> <sup>#</sup>		<u>68</u> <sup>#</sup>	Steady Flow	
10 minutes	<u>0</u> <sup>#</sup>		<u>68</u> <sup>#</sup>	Surges	
15 minutes	<u>0</u> <sup>#</sup>		<u>68</u> <sup>#</sup>	Down to Nothing <u>X</u>	
20 minutes				Nothing	
25 minutes				Gas <u>X</u>	
30 minutes				Gas & Water	
				Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR \_\_\_\_\_ FRESH \_\_\_\_\_ SALTY \_\_\_\_\_ SULFUR \_\_\_\_\_ BLACK \_\_\_\_\_

5 MINUTE SHUT-IN BRADENHEAD 0 INTERMEDIATE \_\_\_\_\_

### REMARKS:

Bradenhead had less than 1 pound of pressure upon opening of 1" valve and Blew down to nothing in 2 seconds. no vapor was present.

By Walt  
Field Technician  
(Position)

Witness NONE

E-mail address \_\_\_\_\_

