



NEW MEXICO ENERGY, MINERALS
and
NATURAL RESOURCES
DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178
FAX: (505) 334-6170

www.emnrd.state.nm.us/ocd/District 3/district3.htm

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test June 12, 2007 Operator CDX RIO, LLC API #30-039- 23678


Property Name Jicarilla Cont. 148 Well No. #38 Location: Unit N Section 13 Township 25N Range 5W

Well Status (Shut-In or Producing) Tubing 144[#] Intermediate NA Casing 148[#] Bradenhead 6[#]

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

TIME	PRESSURES:		
	BRADENHEAD	INTERMEDIATE	CASING
5 minutes	<u>0</u>	<u>NA</u>	<u>139</u> [#]
10 minutes	<u>0</u>	<u>NA</u>	<u>137</u> [#]
15 minutes	<u>0</u>	<u>NA</u>	<u>138</u> [#]
20 minutes	<u>END OF TEST</u>		
25 minutes			
30 minutes			

BRADENHEAD FLOWED	INTERMEDIATE FLOWED
Steady Flow	
Surges	
Down to Nothing <u>X</u>	
Nothing	
Gas	
Gas & Water	
Water	



If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN BRADENHEAD 0 INTERMEDIATE _____

REMARKS: BH had 6[#], bled off to zero in 40 seconds, No action after blow down. (plunger came up during test resulting in tubing and casing pressure fluctuation.).

By Bobby R. Hatchman
Prod. Tech.
(Position)

Witness None

E-mail address _____