



NEW MEXICO ENERGY, MINERALS
and
NATURAL RESOURCES
DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178
FAX: (505) 334-6170
www.emnrd.state.nm.us/ocd/District 3/district3.htm

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test 6-22-2007 Operator CDX RIO, LLC API #30-039- 23697

Property Name Jicarilla Cont. 148 Well No. 40 Location: Unit 4 Section 13 Township 25N Range 5W

Well Status (Shut-In) or Producing) Tubing 1130 # Intermediate N/A Casing 140 # Bradenhead 3 #

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

TIME	PRESSURES:		
	BRADENHEAD	INTERMEDIATE	CASING
5 minutes	<u>0</u>		<u>140</u> #
10 minutes	<u>0</u>		<u>140</u> #
15 minutes	<u>0</u>		<u>140</u> #
20 minutes	<u>0</u>		<u>140</u> #
25 minutes	<u>~ END OF TEST ~</u>		
30 minutes			

	BRADENHEAD FLOWED	INTERMEDIATE FLOWED
Steady Flow		
Surges		
Down to Nothing	<u>X</u>	
Nothing		
Gas		
Gas & Water		
Water		

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN BRADENHEAD 0 INTERMEDIATE _____

REMARKS: Bradenhead bled down to nothing after 1" valve was
opened.

By W. A. [Signature]

Witness _____

Field Technician

(Position)

E-mail address _____

