

E-mail address_

NEW MEXICO ENERGY, MINERALS and NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178
FAX: (505) 334-6170

www.emnrd.state.nm.us/ocd/District 3/district3.htm

	EAD TEST REPORT copies to above address)	
Date of Test 6.15.07 Operator Property Name J; carilla Apan Well No. 8		フ 9 hipRange_ <i>ソル</i>
Well Status (Shut-In or Producing) Tubing 120	Intermediate Casing 140 Bradenl	nead
OPEN BRADENHEAD AND INTERMEDIATE T	O ATMOSPHERE INDIVIDUALLY FOR 1:	5 MINUTES EACH
PRESSURES: TIME <u>BRADENHEAD</u> INTERMEDIATE CASING	BRADENHEAD FLOWED	INTERMEDIATE FLOWED
5 minutes 0 140	Steady Flow	
10 minutes 0 /40	Surges	
15 minutes / 140	Down to Nothing	
20 minutes	Nothing	
25 minutes_	Gas	B
30 minutes	Gas & Water	
	Water	277223242526
If bradenhead flowed water, check all of the descriptions	s that apply below:	RECEIL
CLEAR FRESH SALTY	SULFURBLACK	SON SON SON
5 MINUTE SHUT-IN BRADENHEAD O	INTERMEDIATE	27223242526 PECEIVED SEL SUI 2007. SEL SUI 2007.
	· · · · · · · · · · · · · · · · · · ·	
NO pressure		
By Teonad Luew Pumper (Position)	Witness	