

## NEW MEXICO ENERGY, MINERALS and NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION AZTEC DISTRICT OFFICE 1000 RIO BRAZOS ROAD AZTEC NM 87410 (505) 334-6178 FAX: (505) 334-6170

www.emnrd.state.nm.us/ocd/District 3/district3.htm

## **BRADENHEAD TEST REPORT**

(Submit 2 copies to above address)

Date of Test <u>6-6-07</u> (	Operator_	CDX RIO, LLC_API #30-039- <i>213</i>	22
Property Name Jilarillo Apacho Well	No. <u>26</u>	Location: Unit <u>f</u> Section <u>o</u> To	wnshi <b>p.6N</b> Range 4W
Well Status (Shut-In or Froducing) Tub	ing <u>30</u>	Intermediate Casing 7.5 Brace	denhead
OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH			
PRESSURES: TIME BRADENHEAD INTERMEDIATE	CASING	BRADENHEA FLOWED	D INTERMEDIATE FLOWED
5 minutes O	75	Steady Flow	
10 minutes O	75	Surges	
15 minutes 8	75	Down to Nothing	
20 minutes		Nothing X	
25 minutes		Gas	
30 minutes		Gas & Water	192232426
		Water	802 D. A POES
If bradenhead flowed water, check all of the descriptions that apply below:  CLEAR SEE FRESH SALTY SHIFTIR BLACK			
Gas & Water     Water			
The Dist of the Control of the Contr			
5 MINUTE SHUT-IN BRADENHEAD O INTERMEDIATE INTERMEDIATE			
REMARKS:			
Nu pressure			
By Long Lices		Witness	
By Leonard Lucene Pumper		Without	
(Position)			
E-mail address_			