

NEW MEXICO ENERGY, MINERALS and NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION AZTEC DISTRICT OFFICE 1000 RIO BRAZOS ROAD AZTEC NM 87410 (505) 334-6178

FAX: (505) 334-6170 www.emnrd.state.nm.us/ocd/District 3/district3.htm

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

_	or_CDX RIO, LLCAPI #30-039 2/4 o 3
Property Name <u>Jiear://a Apache</u> Well No. 2	Location: Unit D Section 3 Township Range 4W
Well Status (Shut-In or Producing) Tubing 28	F Intermediate Casing 9 Bradenhead 0
OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH	
PRESSURES: TIME BRADENHEAD INTERMEDIATE CASIN	BRADENHEAD INTERMEDIATE FLOWED FLOWED
5 minutes 0 9	Steady Flow
10 minutes 0 9	Surges
15 minutes 0 9	Down to Nothing
20 minutes	Nothing X
25 minutes	Gas
30 minutes	Gas & Water
	Water
If bradenhead flowed water, check all of the descriptions that apply below:	
CLEAR FRESH SALTY	SULFUR BLACK
5 MINUTE SHUT-IN BRADENHEAD INTERMEDIATE INTERMEDIATE	
Water	
No pressure O	
By Leonaud Lucky	Witness
By Leonaud Tuene Sumpu	
(Position)	•
E-mail address	