

## NEW MEXICO ENERGY, MINERALS and NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178
FAX: (505) 334-6170

www.emnrd.state.nm.us/ocd/District 3/district3.htm

## **BRADENHEAD TEST REPORT**

(Submit 2 copies to above address)

Date of Test 6-4-07 Operator	CDX RIO, LLC_API #30-0392/8 52	
Property Name Jearillo Apache Well No. 16	61-Location: Unit M Section 10 Township 261 Range 4	n
Well Status (Shut-In or Producing) Tubing 50	Intermediate – Casing 80 Bradenhead 10	
OPEN BRADENHEAD AND INTERMEDIATE T	TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH	
PRESSURES: TIME BRADENHEAD INTERMEDIATE CASING	BRADENHEAD INTERMEDIATI G FLOWED FLOWED	E
5 minutes 0 80	Steady Flow	
10 minutes 0 80	Surges	_
15 minutes 0 80	Down to Nothing 🗡	
20 minutes	Nothing	_
25 minutes	Gas K	-
30 minutes	Gas & Water	
	Water	_
If bradenhead flowed water, check all of the description	SULFUR BLACK	
CLEAP FRESH SALTY	_ SULFUR BLACK SULFUR BLACK SULFUR BLACK SULFUR SULFUR SULFUR SULFUR BLACK SULFUR	
5 MINUTE SHUT-IN BRADENHEAD	INTERMEDIATE	
REMARKS:	Water	
Blew down 2 sec		_
		_
		_
Pumper	Witness_	_
Pumper		
(Position)		
F-mail address		