



NEW MEXICO ENERGY, MINERALS  
and  
NATURAL RESOURCES  
DEPARTMENT

OIL CONSERVATION DIVISION  
AZTEC DISTRICT OFFICE  
1000 RIO BRAZOS ROAD  
AZTEC NM 87410  
(505) 334-6178  
FAX: (505) 334-6170  
www.emnrd.state.nm.us/ocd/District 3/district3.htm

**BRADENHEAD TEST REPORT**

(Submit 2 copies to above address)

Date of Test 6-18-07 Operator CDX RIO, LLC API #30-039- 22086

Property Name SIC Cont. 147 Well No. 3E Location: Unit P Section 6 Township 25N Range 5W

Well Status (Shut-In or Producing) Tubing 0 Intermediate - Casing 3 Bradenhead 2

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

TIME	PRESSURES:			BRADENHEAD FLOWED	INTERMEDIATE FLOWED
	BRADENHEAD	INTERMEDIATE	CASING		
5 minutes	<u>0</u>		<u>2</u>	Steady Flow	
10 minutes	<u>0</u>		<u>2</u>	Surges	
15 minutes	<u>0</u>		<u>2</u>	Down to Nothing ✓	
20 minutes				Nothing	
25 minutes				Gas	
30 minutes				Gas & Water	
				Water	


If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR \_\_\_\_\_ FRESH \_\_\_\_\_ SALTY \_\_\_\_\_ SULFUR \_\_\_\_\_ BLACK \_\_\_\_\_

5 MINUTE SHUT-IN BRADENHEAD 0 INTERMEDIATE \_\_\_\_\_

REMARKS:

Down Hole problems



By GROVER VIGIL

Witness \_\_\_\_\_

Pumper  
(Position)

E-mail address \_\_\_\_\_