

## NEW MEXICO ENERGY, MINERALS and NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178
FAX: (505) 334-6170

www.emnrd.state.nm.us/ocd/District 3/district3.htm

## **BRADENHEAD TEST REPORT**

(Submit 2 copies to above address)

Date of Test_	6-14-0	7	Operator_	CDX RIO, LLC_API	#30-039225	79
Property Name Ticavilla B Well No. 2E Location: Unit J Section 16 Township 2N Range 5to						
Well Status (Shut-In or Producing) Tubing 107 Intermediate Casing 110 Bradenhead 3						
OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH						
TIME BRA		PRESSURES: INTERMEDIATE	CASING		BRADENHEAD FLOWED	INTERMEDIATE FLOWED
5 minutes	Ø		110	_ Steady Flow		
10 minutes	Ø		110	Surges		
15 minutes	Ø		110	_ Down to Nothing	<u> </u>	
20 minutes				Nothing	,	
25 minutes				Gas		
30 minutes				Gas & Water	,	
				Water		
If bradenhead flowed water, check all of the descriptions that apply below:						
CLEAR FRESH SALTY SULFUR BLACK & RECEIVED						
Water  If bradenhead flowed water, check all of the descriptions that apply below:  CLEAR FRESH SALTY SULFUR BLACK  5 MINUTE SHUT-IN BRADENHEAD INTERMEDIATE  REMARKS: 2 10 (12) (000) 11 1 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2						
REMARKS: DI						
REMARKS: Blew down in 3 Seconds						
						· · · · · · · · · · · · · · · · · · ·
			·			
	1	,	<u></u>			
By Day	1-1-1	awisou		Witness		
(Position)	i lect	1	<del></del>			
E-mail address						