

NEW MEXICO ENERGY, MINERALS and NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178
FAX: (505) 334-6170
www.emnrd.state.nm.us/ocd/District 3/district3.htm

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test_	6-14-6	07 (Operator_0	CDX RIO, LLC_API	#30-03922	895
Property Name	Jican	rilla B Well	No. 7E	Location: Unit	Section <u>l</u> Towr	nship <u>2UN</u> Range <u>5</u> U
Well Status (S	hut-In or	Producing) Tub	ing <i>]]</i> 24	Intermediate - Cas	sing/65 Brader	nhead 💋
OPEN BRAI	DENHEAL	AND INTERME	DIATE TO	ATMOSPHERE INDI	VIDUALLY FOR	15 MINUTES EACH
TIME BRAI	DENHEAD	PRESSURES: INTERMEDIATE	CASING		BRADENHEAD FLOWED	INTERMEDIATE FLOWED
5 minutes	Ø		165	Steady Flow		
10 minutes	Ø		165	Surges		
15 minutes	Ø		165	_ Down to Nothin	g	-
20 minutes				Nothing		
25 minutes				Gas		
30 minutes				Gas & Water	`	
				Water		232426
If bradenhead flo	wed water.	check all of the des	scriptions tl	nat apply below:	2022	27720-1252623
CLEAR_	FR	ESHSALT	Y	SULFUR BLACK	7.87	RECEIVED 30 31
Water						
REMARKS:		,			Or CI 21	1401601994
			•			
	. (,	
By Duane	Ha	vvison		Witness		
Fiel	d Tec	ch				
(Position) E-mail address						
~ uddi 000						