

NEW MEXICO ENERGY, MINERALS and NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178
FAX: (505) 334-6170

www.emnrd.state.nm.us/ocd/District 3/district3.htm

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test 6.19.07 Operator	_CDX RIO, LLCAPI #30-039 <i>23/98</i>
Property Name Well No. 15A Location: Unit L Section 9 Township Wange 4W	
Well Status (Shut-In or roducing) Tubing 60	Intermediate Casing 90 Bradenhead 5
OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH	
PRESSURES: TIME BRADENHEAD INTERMEDIATE CASING	BRADENHEAD INTERMEDIATE FLOWED FLOWED
5 minutes 90	Steady Flow
10 minutes 90	Surges
15 minutes 0 90	Down to Nothing
20 minutes	NothingX
25 minutes_	Gas
30 minutes	Gas & Water Water Sulfur Black Gas & Water RECEIVED Control RECEIVED Control RECEIVED Control RECEIVED Control RECEIVED
	Water
If bradenhead flowed water, check all of the descriptions that apply below:	
CLEAR FRESH SALTY SULFUR BLACK CLEAR SALTY_ SULFUR BLACK CLEAR SALTY_ SULFUR BLACK CLEAR SALTY_ SULFUR BLACK CLEAR SULFUR_ SULF	
CLEAR FRESH SALTY SULFUR BLACK 5 MINUTE SHUT-IN BRADENHEAD INTERMEDIATE	
5 MINUTE SHUT-IN BRADENHEAD INTERMEDIATE INTERMEDIATE CIC CONS. DIV. DIST. 3 REMARKS:	
2 sec down to nothing	
•	
	,
By Jonard Julins	Witness
(Position)	
E-mail address	