



NEW MEXICO ENERGY, MINERALS
and
NATURAL RESOURCES
DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178
FAX: (505) 334-6170
www.emnrd.state.nm.us/ocd/District 3/district3.htm

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test 6.14.07 Operator CDX RIO, LLC API #30-039- 27833

Property Name Jicavilla "B" Well No. 7F Location: Unit Section 16 Township 26N Range 5W

Well Status (Shut-In or Producing) Producing Tubing 223 Intermediate Casing 338 Bradenhead 3

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

TIME	PRESSURES:				
	BRADENHEAD	INTERMEDIATE	CASING	BRADENHEAD FLOWED	INTERMEDIATE FLOWED
5 minutes	<u>Ø</u>		<u>338</u>	Steady Flow <u> </u>	
10 minutes	<u>Ø</u>		<u>338</u>	Surges <u> </u>	
15 minutes	<u>Ø</u>		<u>338</u>	Down to Nothing <u>X</u>	
20 minutes				Nothing <u> </u>	
25 minutes				Gas <u>X</u>	
30 minutes				Gas & Water <u> </u>	
				Water <u> </u>	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN BRADENHEAD B INTERMEDIATE

REMARKS:

Blew down in 3 seconds



By Duane Harrison

Witness

(Position)

E-mail address