



NEW MEXICO ENERGY, MINERALS  
and  
NATURAL RESOURCES  
DEPARTMENT

OIL CONSERVATION DIVISION  
AZTEC DISTRICT OFFICE  
1000 RIO BRAZOS ROAD  
AZTEC NM 87410  
(505) 334-6178  
FAX: (505) 334-6170  
www.emnrd.state.nm.us/ocd/District 3/district3.htm

**BRADENHEAD TEST REPORT**

(Submit 2 copies to above address)

Date of Test 6-22-07 Operator CDX RIO, LLC API #30-039- 29664

Property Name Tic Apache 102 Well No. 9F Location: Unit 6 Section 4 Township 26N Range 4W

Well Status (Shut-In or Producing) Tubing 60 Intermediate — Casing 120 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

TIME	PRESSURES:			BRADENHEAD FLOWED	INTERMEDIATE FLOWED
	BRADENHEAD	INTERMEDIATE	CASING		
5 minutes	<u>0</u>		<u>120</u>	Steady Flow	
10 minutes	<u>0</u>		<u>120</u>	Surges	
15 minutes	<u>0</u>		<u>120</u>	Down to Nothing	
20 minutes				Nothing <u>X</u>	
25 minutes				Gas	
30 minutes				Gas & Water	
				Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR — FRESH — SALTY — SULFUR — BLACK —

5 MINUTE SHUT-IN BRADENHEAD 0 INTERMEDIATE —

REMARKS:

No Pressure 0

By Leonard Lunn

Witness —

(Position)

E-mail address —

