## submitted in lieu of Form 3160-5

## UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

	Sundry Notices and Reports on Wells	2007 JUL	17 pm	D. 115	
1.	Type of Well GAS	£.	5.	3: 43 Lease Number NMSF-080670 If Indian, All. or ATribe Name	
2. '	Name of Operator		7.	Unit Agreement Name	
	BURLINGTON RESCURCES OIL & GAS COMPANY LP			San Juan 27-4 Unit	
3.	Address & Phone No. of Operator		8.	Well Name & Number	
	PO Box 4289, Farmington, NM 87499 (505) 326-9700	· · · · · · · · · · · · · · · · · · ·	9.	SJ 27-4 Unit #46G API Well No. 30-039-3026	
4.	Location of Well, Footage, Sec., T, R, M		10.	Not assigned yet  Field and Pool	
	Unit A (NENE), 1324' FNL & 452' FEL, Sec. 31, T27N R4W, NMPM			Basin Dakota	
	Cinter (HEILE), 1524 That to 452 Feb., 500. 51, 1271 R411, HIRIN		11.	County and State Rio Arriba Co., NM	
12. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OT  Type of Submission  X Notice of Intent Abandonment Recompletion Subsequent Report Plugging Non-Routine Fracturing Casing Repair Water Shut off Final Abandonment Altering Casing Conversion to Injection				THER DATA  ther – Cancel pending APD	
The Bur	subject well's plat was wrong and then we decided to drill the subject well dialington Resources wishes to rescind the APD submitted 5/17/07 since so much use return the APD to us and we will re-submit the APD with the correct footage.  New API?	of the API	) is current	tly incorrect.	
14. Sign	I hereby certify that the foregoing is true and correct.  ned	ory Speciali	st Date	e 7/16/07 .	
API COl	is space for Federallor State Office use  PROVED BY			Date 07/18/07	

