



# NEW MEXICO ENERGY, MINERALS and NATURAL RESOURCES DEPARTMENT

## MECHANICAL INTEGRITY TEST REPORT

(TA OR UIC)

Date of Test Aug 13, 2007 Operator J.H. Intervent 1 LTD API # 30-045-29160

Property Name West Bisti 26-13-17 Well # 001 Location: Unit A Sec 17 Twn 26 Rge 13

Land Type:

State \_\_\_\_\_  
Federal ☒ \_\_\_\_\_  
Private \_\_\_\_\_  
Indian \_\_\_\_\_

Well Type:

Water Injection \_\_\_\_\_  
Salt Water Disposal \_\_\_\_\_  
Gas Injection \_\_\_\_\_  
Producing Oil/Gas ☒ \_\_\_\_\_  
Pressure observation \_\_\_\_\_

Temporarily Abandoned Well (Y/N): \_\_\_\_\_ TA Expires: \_\_\_\_\_

Casing Pres. \_\_\_\_\_  
Headhead Pres. \_\_\_\_\_  
Tubing Pres. \_\_\_\_\_  
Int. Casing Pres. \_\_\_\_\_

Tbg. SI Pres. \_\_\_\_\_  
Tbg. Inj. Pres. \_\_\_\_\_

Max. Inj. Pres. \_\_\_\_\_

Pressured annulus up to \_\_\_\_\_ psi. for \_\_\_\_\_ mins. Test passed/failed failed

### REMARKS:

4 attempts all failed

Top Perf @ 1443'  
CIBP @ 1430'

RCVD AUG 13 '07

OIL CONS. DIV.

DIST. 3

By M. Smith  
(Operator Representative)

Witness Shelly Cowden  
(NMOCD)

Consultant  
(Position)

Placed 100' Cement on top of CIBP Per Phone Call from M.L. Smith  
will Retest 8/14/07 10:00AM  
860-2241 @ 3:00PM  
8/13/07

Oil Conservation Division \* 1000 Rio Brazos Road \* Aztec, New Mexico 87410  
Phone: (505) 334-6178 \* Fax (505) 334-6170 \* <http://www.emnrd.state.nm.us>

6 AM

5

4

3

2

1

NOON

1

2

3

4

5

6 PM

7

8

9

10

11

MIDNIGHT

1

2

3

4

5

6

7


8

9

10

11

12



Shelley Carter

NOON

GRAPHIC CONTROLS CORPORATION  
BUFFALO, NEW YORK

CHART NO. MC MP-1000-100F  
Aug. 13, 2007

CHART PUT ON  
TAKEN OFF

LOCATION  
West Best 26-13-17

REMARKS  
#001

RCVD AUG 13 '07

OIL CONS. DIV.

DIST. 3