



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnr.state.nm.us/ocd/District III/3district.htm](http://emnr.state.nm.us/ocd/District%20III/3district.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 8-20-07 Operator ConocoPhillips API #30-0 39-07448
Property Name Sun Juan 287 Well No. 74 Location: Unit N Section 11 Township 28 Range 7
Well Status (Shut-In or Producing) Producing Initial PSI: Tubing 88 Intermediate 90 Casing 90 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE				
	BH	Bradenhead		INTERM	
		Int	Csg	Int	Csg
TIME					
5 min					85
10 min					83
15 min					81
20 min					80
25 min				10	79
30 min				14	78

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	✓
Surges	
Down to Nothing	✓
Nothing	
Gas	✓
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

RCVD AUG 20 '07
OIL CONS. DIV.
DIST. 3

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0

INTERMEDIATE 71

REMARKS:

Bradenhead down in 5 seconds through
a 1/2 in pipe
Intermediate blew whole time.

By Dan Braun

Witness Monica Kuehling

(Position)

E-mail address _____

Failure