Form 3160-5 (November 1994)

UNITED STATES DEPARTMENT OF THE INTERIOR **BUREAU OF LAND MANAGEMENT**

SUNDRY NOTICES AND REPORTS ON WELLS

FORM APPROVED
OMB No. 1004-0135
Expires July 31, 1996

Lease Serial No.

	NM-18316		
If Kndian,	Allottee or Tribe Name		

Do not use this form for proposals to drill or reenter an			6. If Indian, Allottee or Tribe Name	
abandoned well.	Use Form 3160-3 (API	D) for such proposal	S.	17 PH 1. 11
OUDIET IN TOISE				7. If Unit or CA/Agreement, Name and or No
	ICATE – Other instr	ructions on revers	e side	210 FAFFIH STOY MAY
1. Type of Well				TON MA.
Oil Well X Gas Well Other			8. Well Name and No.	
2. Name of Operator				Carson 29-04-11 No. 2
Black Hills Gas Resources	s, Inc. c/o Mike	e Pippin LLC (Agent)	9. API Well No.
Ba. Address		3b. Phone No. (includ	e area code)	30-039-20649
3104 N. Sullivan, Farmington	on, NM 87401	505-327-4573		10. Field and Pool, or Exploratory Area
4. Location of Well (Footage, Sec., T	., R., M., or Survey Description	on)		Chosa Mesa Pictured Cliffs
Surface: 1770' FNL & 944' FEL Unit H Sec. 11, T29N, R4W		AND		
Bottom Hole: 1617' FNL & 1629' FWL Unit F Sec. 11, T29N. R4W			Rio Arriba County, New Mexico	
12. CHECK APPROPRIATE BOX	K(ES) TO INDICATE NA	TURE OF NOTICE, RI	EPORT, OR OT	THER DATA
TYPE OF SUBMISSION	TYPE OF ACTION			
Notice of Intent	Acidize	Deepen	Production	(Start/Resume)
	Alter Casing	Fracture Treat	Reclamatio	n Well Integrity
Subsequent Report	Casing Repair	☐ New Construction	Recomplete	Other Install Pumping
	Change Plans	Plug and Abandon		
Final Abandonment Notice	Convert to Injection	☐ Plug Back	☐ Water Disp	osal
104 N. Sullivan, Farmington, NM 87401 Location of Well (Footage, Sec., T., R., M., or Survey Description) Inface: 1770' FNL & 944' FEL Unit H Sec. 11. T29N. R4W Ottom Hole: 1617' FNL & 1629' FWL Unit F Sec. 11, T29N. R4W CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA TYPE OF SUBMISSION TYPE OF ACTION Notice of Intent Acidize Deepen Production (Start/Resume) Alter Casing Fracture Treat Reclamation Well Integrity Subsequent Report To the d and Pool, or Exploratory Area Chosa Mesa Pictured Cliffs AND Rio Arriba County, New Mexico Rio Arriba County, New Mexico Production (Start/Resume) Water Shut-Off Alter Casing Fracture Treat Reclamation Well Integrity New Construction Recomplete				

Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days Following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once Testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the size is ready for final inspection.)

7/16/07: MIRUSU. TOH w/2-3/8" tbg. Landed 2-3/8" 4.7# J-55 tbg @ 3681'. Ran pump & rods & prepaired to pump well. Released rig on 7/18/07.

> RCVD SEP 4'07 OIL CONS. DIV. DIST. 3

Permit				
Name (Printed/Typed)	Title			
Mike Pippin	Petrole	Petroleum Engineer (Agent)		
Signature Mile Less	Date in	July 25, 2007		
	THIS SPACE FOR FEDERAL OR STATE USE	ACCEPTED	FOR RECORD	
Approved by	Title	Date	- THEOCH!	
Conditions of approval, if any, are attached. Approval of the certify that the applicant holds legal or equitable title to the which would entitle the applicant to conduct operations then	se nghts in the subject lease	AUG 2	9 2007	

(Instructions on reverse)

fraudulent statements or representations as to any matter within its jurisdiction.

