

NEW MEXICO ENERGY, MINERALS and NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION AZTEC DISTRICT OFFICE 1000 RIO BRAZOS ROAD AZTEC NM 87410 (505) 334-6178 FAX: (505) 334-6170

www.emnrd.state.nm.us/ocd/District 3/district3.htm

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test08/28/07Operator_Mine	el IncAPI #30-039-22872
Property NameCayias Well No#1	Location: Unit G_Section 2Township 25Range 3
Well Status (Shut-In or <u>Producing</u>) Tubing	Intermediate Casing 19 Bradenhead_0
OPEN BRADENHEAD AND INTERMEDIATE	E TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH
PRESSURES: TIME <u>BRADENHEAD INTERMEDIATE</u> CASI	BRADENHEAD INTERMEDIATE NG FLOWED FLOWED
5 minutes	Steady Flow
10 minutes	Surges
15 minutes	Down to Nothing
20 minutes	Nothing XX
25 minutes	Gas
30 minutes	Gas & Water
	Water
If bradenhead flowed water, check all of the descripti	ions that apply below:
CLEAR FRESH SALTY	SULFUR BLACK (& RECEIVED ನ\
5 MINUTE SHUT-IN BRADENHEAD	Gas & Water Water Sulfur BLACK INTERMEDIATE Water 123456 > 00000000000000000000000000000000000
REMARKS:	18/19202122233
ByJoe Elledge	Witness_
Agent/Foreman(Position)	
E-mail address	· -