

## NEW MEXICO ENERGY, MINERALS and NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178
FAX: (505) 334-6170
www.emnrd.state.nm.us/ocd/District 3/district3.htm

## **BRADENHEAD TEST REPORT**

(Submit 2 copies to above address)

Date of Test08/27/07 Operator_McElvain Oil and GasAPI #30-039-26669	
Property NameCougar Com 33_Well No#1M_Location: Unit_M_Section_33_Township_26_Range_2_	
Well Status (Shut-In or <u>Producing</u> ) Tubing_0_	Intermediate Casing_156 Bradenhead0
OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH	
PRESSURES: TIME BRADENHEAD INTERMEDIATE CASING	BRADENHEAD INTERMEDIATE  G FLOWED FLOWED
5 minutes	Steady Flow
10 minutes_	Surges
15 minutes .	Down to Nothing
20 minutes	Nothing XX
25 minutes	Gas
30 minutes	Gas & Water
	Water
If bradenhead flowed water, check all of the descriptions that apply below:  RECEIVED	
CLEARFRESHSALTY	SULFUR BLACK (SEP. 2001 5)
5 MINUTE SHUT-IN BRADENHEAD	Water  Water  BLACK  INTERMEDIATE  Water  Water  RECEIVED  RECEIVE
REMARKS:Pump Jack	
ByJoe Elledge	Witness
Agent/Foreman(Position)	
E-mail address	