



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
<http://emnr.state.nm.us/ocd/District III/3distr.htm>

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 9-13-07 Operator ConocoPhillips API # 30-039-22471
Property Name San Juan ^{Unit: 37A} Well No. 2387 Location: Unit 37 Section 29 Township 29 Range 5
Well Status (Shut-In or Producing) Initial PSI: Tubing 116 Intermediate NA Casing 136 Bradenhead 2

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Int	Csg	Int	Csg
TIME					
5 min					
10 min					
15 min					
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	✓
Nothing	
Gas	✓
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

RCVD SEP 13 '07
OIL CONS. DIV.
DIST. 3

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0 INTERMEDIATE N/A

REMARKS: Bradenhead blew down in 4 seconds
5 minute shut in.

By [Signature]
(Position)

Witness Jesse T. Chahamir

E-mail address _____