



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnr.state.nm.us/ocd/District III/3district.htm](http://emnr.state.nm.us/ocd/District%20III/3district.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 9/13-07 Operator Conaco Phillips API #30-0 39-26581
Property Name San Juan 295 Lot Well No. 59M Location: Unit I Section 31 Township 29 Range 5
Well Status (Shut-In or Producing) Initial PSI: Tubing 112 Intermediate 12 Casing 174 Bradenhead 2

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Bradenhead Int	Csg	Int	Csg
TIME					
5 min					<u>174</u>
10 min					<u>174</u>
15 min					<u>174</u>
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	☒
Nothing	
Gas	☒
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

RCVD SEP 13 '07
OIL CONS. DIV.
DIST. 3

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0 INTERMEDIATE 2

REMARKS: Commenced well. Blew down in 1 second.
Intermediate blew down in 1 min. 39 seconds
just did 5 min. Shut in on BH
By Josh J Witness Monica Kuehling
(Position)

E-mail address _____