District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico Energy Minerals and Natural Resources

Form C-144 June 1, 2004

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505 For drilling and production facilities, submit to appropriate NMOCD District Office.
For downstream facilities, submit to Santa Fe office

Is pit or below-grade tank	de Tank Registration or Clost covered by a "general plan"? Yes X below-grade tank Closure of a pit or below-g	No 🗌
Operator:CDX RIO, LLCTelephone: _(505) Address:2010 Afton Place, Farmington, New Mexico 87401 Facility or well name:Jicarılla 102 #10NAPI #:30-039 County:Rio Arriba Latitude36 30' 50.3" Longitude107 15' 46	326-3003e-mail address: nancy.oltr	manns@cdxgas.com Sec4T_26NR_4W
Pit Type: Drilling X Production Disposal Workover Emergency Lined X Unlined D Liner type: Synthetic Thickness 12 mil Clay Pit Volume 13,360 bbl	Below-grade tank Volume:bbl Type of fluid Construction material: Double-walled, with leak detection? Yes	
Depth to ground water (vertical distance from bottom of pit to seasonal high water elevation of ground water.)	Less than 50 feet 50 feet or more, but less than 100 feet 100 feet or more	(20 points) (10 points) (0 points) 0 points
Wellhead protection area: (Less than 200 feet from a private domestic water source, or less than 1000 feet from all other water sources.)	Yes No .	(20 points) (0 points) 0 points
Distance to surface water: (horizontal distance to all wetlands, playas, irrigation canals, ditches, and perennial and ephemeral watercourses.)	Less than 200 feet 200 feet or more, but less than 1000 feet 1000 feet or more	(20 points) (10 points) (0 points) 0 points 0 points
If this is a pit closure: (1) attach a diagram of the facility showing the pit's your are burying in place) onsite X ☐ offsite ☐ If offsite, name of facility remediation start date and end date (4) Groundwater encountered: No X ☐ Attach soil sample results and a diagram of sample locations and excavations	Yes I If yes, show depth below ground surface.	eral description of remedial action taken including ft. and attach sample results. (5)
Additional Comments: Pit was backfilled with dirt. Pit remediation was sta	arted approximately 8-31-07. Pit was closed 9-5-07	RCUD SEP 10'07
		DIST. 3
I hereby certify that the information above is true and complete to the best of been/will be constructed or closed according to NMOCD guidelines, Date:9-6-07	a general permit X , or an (attached) alternat Signature ot relieve the operator of liability should the contente operator of its responsibility for compliance with	ive OCD-approved plan
Approval: Deputy Oil & Gas Inspector Printed Name/Title District #3	or, Signature BAL AM	SEP 2 1 2007


CDX Rio, LLC

2010 Afton Place Farmington NM 87401 505-326-3003

Lease: Jic. 102

Well: Jic. 102 #10N

Location: NE/4, SW/4, S4 - T26N - R4W



General sealing of valve, sales by tank guaging:

Production phase: All drain valves (D1 and D2) and all sales valves (S1 and S2) are sealed closed.

Sales phase: The tank from which sales are being made will be isolated by sealing closed the drain valve, fill valve, and the equalizer valve during sales.

Draining phase: The tank being drained will be isolated by sealing closed the sales valve, fill valve, and equalizer valve during draining, and sales valve and drain valve on the other tank(s).

This lease is subject to the Site Security Plan for Southern Rockies Operations and is located in our Farmington, NM office.