



NEW MEXICO ENERGY, MINERALS and
NATURAL RESOURCES DEPARTMENT

MECHANICAL INTEGRITY TEST REPORT

~~(TA)~~ OR (UIC)

Date of Test Oct 10, 2003 Operator BC & D Operating Inc API # 30-031-20150

Property Name Santa Fe Railroad Well # 23 Location: Unit C Sec 7 Twn 17 Rge 8

Land Type:

State _____
Federal _____
Private X _____
Indian _____

Well Type:

Water Injection X _____
Salt Water Disposal _____
Gas Injection _____
Producing Oil/Gas _____
Pressure observation _____

Temporarily Abandoned Well (Y/N): N TA Expires: —

Casing Pres. _____ Tbg. SI Pres. _____ Max. Inj. Pres. _____
Bradenhead Pres. _____ Tbg. Inj. Pres. _____
Tubing Pres. _____
Int. Casing Pres. _____

Pressured annulus up to 410 psi. for 30 mins. Test passed failed


REMARKS:

By [Signature] BC & D
(Operator Representative)

Witness [Signature]
(NMOCD)

Supervisor
(Position)

Revised 02-11-02



GRAPHIC CONTROLS CORPORATION
BUFFALO, NEW YORK

CHART NO. MC MP-1000
Oct 10, 2003

METER _____
TAKEN OFF P M
CHART PUT ON P M
12:50 P M
LOCATION BC & D Operating Area
Santa Fe Railroad #23
REMARKS APT # 30-031-20150

Donut Tiller B-10

PRINTED IN U.S.A.