

MEW MEXICO EMERGY, MUNERALS & MAJURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION AZTEC DISTRICT OFFICE 1000 RIO BRAZOS ROAD AZTEC NM 87410

(505) 334-6178 FAX: (505) 334-6170 http://emnrd.state.nm.us/ocd/District IIV3distric htm

BRADENHEAD TEST REPORT

(submit 2 copies to above address)

Date of Test_	8-14-07	Operator	Kimbell operating	_API #30-0 <u>.3 9</u> ~	23061
			Location: Unit GS		
Well Status(S	Shut-In or Producin	Tubing 118	Intermediate Casi	ng <u>142</u> Bradenh	ead <u>()</u>
OPEN BRA	ADENHEAD AND I	NTERMEDIATE 1	O ATMOSPHERE INDIV	VIDUALLY FOR 15	MINUTES EACH
TIME	PRESSURES: INTERMEDIATE	CASING		BRADENHEAD FLOWED	INTERMEDIATE FLOWED
5 minutes	O	142	Steady Flow		
10 minutes	0	142	Surges		
15 minutes	_	142	Down to Nothing	g/	
20 minutes	^	142	Nothing	/	
25 minutes	\wedge	142	Gas		
30 minutes	\circ	142	Gas & Water		
			Water		23456789
If bradenhead i	flowed water, check a	l of the description	s that apply below:	(S)	OII
			BLAC	CK 011	23456789 PECHIVED 3 OCT. 2007 CONS. DIV. DIST. 3
CLL		0.12.1	_ 562.61	/23 OII	CONS. DIV. DIST. 3
5 MINUTE SHUT-IN BRADENHEAD INTERMEDIATE					
REMARKS:				~	55512020212233
					`
	· · · · · · · · · · · · · · · · · · ·				
By Earl	North		SS		
Pumper (Position	on)				