

## NEW MEXICO ENERGY, MINERALS and NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178
FAX: (505) 334-6170

www.emnrd.state.nm.us/ocd/District 3/district3.htm

## **BRADENHEAD TEST REPORT**

(Submit 2 copies to above address)

Date of Test $\frac{4-21}{}$	05 c	Operator	DEVON AP	I #30-0 <u><i>39 -</i></u>	07830
Property Name NEBU Well No. 10 Location: Unit M Section 16 Township 30 N Range 7 W					
Well Status (Shut-In or Producing) Tubing 75 Intermediate / Casing 8/ Bradenhead 6					
OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH					
TIME BRADENHEAD	PRESSURES: INTERMEDIATE	CASING		ADENHEAD LOWED	INTERMEDIATE FLOWED
5 minutes 6	0	82	Steady Flow		
10 minutes	0	83	Surges		
15 minutes 6		83	Down to Nothing		V
20 minutes_			Nothing		
25 minutes			Gas		
30 minutes			Gas & Water		
Water					
If bradenhead flowed water, check all of the descriptions that apply below:					
CLEAR FRESH SALTY SULFUR BLACK					
5 MINUTE SHUT-IN BRADENHEAD 6 INTERMEDIATE 0					
REMARKS:					
		·			
By Kenneth W Vanghan Witness_					
CONTRACTOR ARK SALES & SERVICES INC. (Position)					
E-mail address					