

## NEW MEXICO ENERGY, MINERALS and NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178
FAX: (505) 334-6170

www.emnrd.state.nm.us/ocd/District 3/district3.htm

## **BRADENHEAD TEST REPORT**

(Submit 2 copies to above address)

Date of Test 4/20/05	Operator_	Devon	_API #30-0 <u>_39</u>	22472
Property Name <u>NEGU</u> Well No. <u>13 A</u> Location: Unit <u>C</u> Section <u>20</u> Township <u>30-1</u> Ránge <u>7 W</u>				
Well Status (Shut-In or Producing) Tubing 2 Intermediate 0 Casing 2 Bradenhead 0				
OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH				
PRESSUR TIME <u>BRADENHEAD INTERM</u>			BRADENHEAD FLOWED	INTERMEDIATE FLOWED
5 minutes O	) 2	Steady Flow		
10 minutes O	0 2	Surges		Typing and an analysis and an an analysis and
15 minutes O	0 2	Down to Nothing	3 1	
20 minutes		Nothing		
25 minutes		Gas		
30 minutes		Gas & Water		
		Water		
If bradenhead flowed water, check all of the descriptions that apply below:				
CLEAR FRESH SALTY SULFUR BLACK				
5 MINUTE SHUT-IN BRADENHEAD 5 INTERMEDIATE 6				
By Kenneth W. Vaughan Witness				
By Rennett W. Vaugher Witness  Contractor - ARK Sales & Services INC  (Position)				
E-mail address				