



NEW MEXICO ENERGY, MINERALS
and
NATURAL RESOURCES
DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178
FAX: (505) 334-6170
www.emnrd.state.nm.us/ocd/District 3/district3.htm

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test 4-22-05 Operator Dewon API #30-0 39-27299
Property Name NEBU Well No. 413A Location: Unit Section 20 Township 30N Range 7W
Well Status (Shut-In or Producing) Tubing 43 Intermediate N/A Casing 44 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

TIME	PRESSURES:			BRADENHEAD FLOWED	INTERMEDIATE FLOWED
	BRADENHEAD	INTERMEDIATE	CASING		
5 minutes	<u>0</u>	<u>N/A</u>	<u>44</u>	Steady Flow	
10 minutes	<u>0</u>		<u>44</u>	Surges	
15 minutes	<u>0</u>		<u>44</u>	Down to Nothing	
20 minutes				Nothing <u>✓</u>	<u>N/A</u>
25 minutes				Gas	
30 minutes				Gas & Water	
				Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN BRADENHEAD 0 INTERMEDIATE N/A

REMARKS:

Reading on The CASING WAS TAKEN From
The LCD - (No Access For Testing Other Than LCD)

By Kenneth W. Vaughan

Witness

Contractor - ARK Sales & Services
(Position)

E-mail address

