



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnrd.state.nm.us/ocd/District III/district.htm](http://emnrd.state.nm.us/ocd/District%20III/district.htm)

BRADENHEAD TEST REPORT

(submit 2 copies to above address)

Date of Test 9-6-07 Operator alpine Oil & Gas
mm Production API #30-0 39-22504

Property Name Tierrilla 13 Well No. 003 Location: Unit A Section 26 Township 24N Range 05W

Well Status (Shut-In or Producing) Tubing 70 Intermediate 0 Casing 74 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

TIME	PRESSURES INTERMEDIATE	CASING	BRADENHEAD FLOWED	INTERMEDIATE FLOWED
5 minutes			Steady Flow	
10 minutes			Surges	
15 minutes	✓	✓	Down to Nothing	
20 minutes			Nothing	✓
25 minutes			Gas	
30 minutes			Gas & Water	
			Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

RCUD NOV 6 '07
OIL CONS. DIV.

DIST. 3

5 MINUTE SHUT-IN BRADENHEAD _____ INTERMEDIATE _____

REMARKS

Well equalize casing & tubing because Enterprise's
line pressure was going up.

By Billy Keetoo
Pumper
(Position)

Witness Laura McCon