



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnrd.state.nm.us/ocd/District III/3distric.htm](http://emnrd.state.nm.us/ocd/District%20III/3distric.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 8-1-07 Operator BLACK HILLS API #30-039 26659

Property Name 29-2-4 Well No. 1 Location: Unit L Section 4 Township 29N Range 02W

Well Status(Shut-In or Producing) Initial PSI: Tubing 0 Intermediate Casing 15 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing TIME	PRESSURE				
	Bradenhead			INTERM	
	BH	Int	Csg	Int	Csg
5 min	<u>0</u>		<u>15</u>		
10 min	<u>0</u>		<u>15</u>		
15 min	<u>0</u>		<u>15</u>		
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	<u>RCUD NOV 2 '07</u>
Down to Nothing	<u>OIL CONS. DIV.</u>
Nothing <u>✓</u>	<u>DIST. 3</u>
Gas	
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0 INTERMEDIATE

REMARKS:

casing did not fall

By Judson Valdez

Witness

lease operator
(Position)

E-mail address

jvaldez@BHEP.com