



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnrd.state.nm.us/ocd/District III/3district.htm](http://emnrd.state.nm.us/ocd/District%20III/3district.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 8-1-07 Operator Black Hills API #30-0 39 26 865

Property Name Jic 29-2-9 Well No. 2 Location: Unit D Section 9 Township 2N Range 02W

Well Status (Shut-In or Producing) Initial PSI: Tubing 6 Intermediate Casing 30 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE				
	Bradenhead			INTERM	
	BH	Int	Csg	Int	Csg
TIME					
5 min	<u>0</u>		<u>30</u>		
10 min	<u>0</u>		<u>30</u>		
15 min	<u>0</u>		<u>30</u>		
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	<u>RCVD NOV 2 '07</u>
Down to Nothing	<u>OIL CONS. DIV.</u>
Nothing <u>✓</u>	<u>DIST. 3</u>
Gas	
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0 INTERMEDIATE

REMARKS:

casing did not Fall

By Judson Valdez

Witness

lease operator
(Position)

E-mail address jvaldez@BHEP.com