



NEW MEXICO ENERGY, MINERALS & NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnrd.state.nm.us/ocd/District III/3district.htm](http://emnrd.state.nm.us/ocd/District%20III/3district.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 9-25-07 Operator Black Hills API #30-0 39 29531

Property Name Mc 29-2-19 Well No. 34 Location: Unit Section 19 Township 24N Range 2W

Well Status (Shut-In or Producing) Initial PSI: Tubing 100 Intermediate Casing 250 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing TIME	PRESSURE				
	Bradenhead			INTERM	
	BH	Int	Csg	Int	Csg
5 min	<u>0</u>		<u>250</u>		
10 min	<u>0</u>		<u>250</u>		
15 min	<u>0</u>		<u>250</u>		
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow <u> </u>	
Surges <u> </u>	
Down to Nothing <u>✓</u>	<u>PCUD NOV 2 '07</u>
Nothing <u> </u>	<u>OIL CONS. DTU</u>
Gas <u> </u>	<u>DIST. 3</u>
Gas & Water <u> </u>	
Water <u> </u>	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0 INTERMEDIATE

REMARKS:

Casing never fell

By Joson Valdez

Witness

Pumper
(Position)

E-mail address JValdez@BHEP.com