

NEW MEXICO OIL CONSERVATION COMMISSION

MISCELLANEOUS REPORTS ON WELLS

(Submit to appropriate District Office as per Commission Rule 1106)

COMPANY A. H. Bernstein, c/o Lloyd D Locke, Durango, Colorado
(Address)

LEASE Allen WELL NO. 1 UNIT F S 23 T 29N R 13W
DATE WORK PERFORMED _____ POOL West Kutz

This is a Report of: (Check appropriate block) ☐ Results of Test of Casing Shut-off
☐ Beginning Drilling Operations ☐ Remedial Work
☒ Plugging ☐ Other _____

Detailed account of work done, nature and quantity of materials used and results obtained.

Cemented 3-1/2" in casing at 1175' w/50 sx cement

Plugged back through Pictured Cliffs and Fruitland with cement by dump baler.

Knocked off 3-1/2" pipe above 350'. Plugged from top of cement to surface with mud. 4" pipe marker set in cement.

FILL IN BELOW FOR REMEDIAL WORK REPORTS ONLY

Original Well Data:

DF Elev. _____ TD _____ PBD _____ Prod. Int. _____ Compl Date _____
Tbng. Dia _____ Tbng Depth _____ Oil String Dia _____ Oil String Depth _____
Perf Interval (s) _____
Open Hole Interval _____ Producing Formation (s) _____

RESULTS OF WORKOVER:

Date of Test

Oil Production, bbls. per day

Gas Production, Mcf per day

Water Production, bbls. per day

Gas-Oil Ratio, cu. ft. per bbl.

Gas Well Potential, Mcf per day

Witnessed by _____



BEFORE

AFTER

_____	_____
_____	_____
_____	_____
_____	_____
_____	_____
_____	_____

(Company)

OIL CONSERVATION COMMISSION

Name A. R. Kendrick
Title Oil and Gas Inspector Dist. #3.
Date SEP 28 1956

I hereby certify that the information given above is true and complete to the best of my knowledge.

Name Lloyd D Locke
Position Agent, Durango, Colorado
Company A. H. Bernstein, Owner