



NEW MEXICO ENERGY, MINERALS & NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnr.state.nm.us/ocd/District III/3distric.htm](http://emnr.state.nm.us/ocd/District%20III/3distric.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 12-6-07 Operator ConocoPhillips SAPI #30-0 45-28703
Property Name San Juan 3284 SW Well No. 303 Location: Unit E Section 14 Township 31 Range 8
Well Status (Shut-In or Producing) Initial PSI: Tubing 2250 Intermediate 1.7 Casing 1825 Bradenhead 378

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Bradenhead Int	Csg	Int	Csg
TIME					
5 min	0	0	1825		
10 min	0	0	1825		
15 min	0	0	1825		
20 min					
25 min					
30 min					

	FLOW CHARACTERISTICS	
	BRADENHEAD	INTERMEDIATE
Steady Flow		
Surges		
Down to Nothing	✓	
Nothing		
Gas	✓	
Gas & Water		DIST. 3
Water		

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

OIL CONS. DIV.

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0 INTERMEDIATE 0

REMARKS:

Bradenhead blew down in 5 minutes through
1/4" Valve.

Intermediate - Dabb

By JACK D. BRECHFIELD

Witness Monica Kuchling

(Position)

E-mail address _____