



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX. (505) 334-6170
[http://emnrd.state.nm.us/ocd/District III/3ddistrict.htm](http://emnrd.state.nm.us/ocd/District%20III/3ddistrict.htm)

BRADENHEAD TEST REPORT

(submit 2 copies to above address)

Date of Test 11-1-07 Operator COULTHURST API #30-0 43-20811
MAINTENANCE
INV. INC
Property Name ANN 19 Well No. 19 Location: Unit 7 Section 33 Township 18N Range 3W
Well Status (Shut-In) or Producing) Tubing Intermediate Casing 0 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

TIME	PRESSURES:		BRADENHEAD FLOWED	INTERMEDIATE FLOWED
	INTERMEDIATE	CASING		
5 minutes		<u>0</u>	Steady Flow	
10 minutes		<u>0</u>	Surges	
15 minutes		<u>0</u>	Down to Nothing	
20 minutes		<u>0</u>	Nothing	
25 minutes		<u>0</u>	Gas	
30 minutes		<u>0</u>	Gas & Water	
			Water	

RCVD JAN 8 '08
OIL CONS. DIV.
DIST. 3

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN BRADENHEAD 0 INTERMEDIATE

REMARKS:

THIS well is being EVALUATED for pressure
MAINTENANCE PURPOSES - NO TUBING IN well

By Phillip Montoya
Pumper
(Position)

Witness