

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(606) 334-9178 FAX: (806) 334-6170
http://emnrd.state.nm.ue/ocd/District III/3distric.htm

BRADENHEAD TEST REPORT

(submit 2 copies to above address)

Date of Test_	1-28-08	Operator_	ENERDYNE LI	_CAPI #30-0_	31-20619
Property Nan	ne CHACO WASH	MV Well No. 011	Location: Unit	A Section 28 To	ownship 20N Range 9W
Well Status(S	Shut-In or Producin	g) Tubing 5/8" I	ntermediate NA	Casing 4.5" Bra	ndenhead NA
OPEN BRA	ADENHEAD AND II	NTERMEDIATE TO	ATMOSPHERE I	NDIVIDUALLY FO	OR 15 MINUTES EACH
PRESSURES:			BRADENHEAD		
INTERMEDIA' TIME	INTERMEDIATE	CASING		FLOWED	FLOWED
5 minutes			Steady Flo	w	
10 minutes			Surges		
15 minutes			Down to Nothing		RCDD JAN 30'08
20 minutes			Nothing Gas		UI_ CONS. DIV.
25 minutes					Ent in the Fig.
			Gas & Water		
			Water		
If bradenhead	flowed water, check a	ll of the descriptions t		•	
CLEA	RFRESH	SALTY	SULFUR	BLACK	
5 MINUTE SHUT-IN BRADENHEAD INTERMEDIATE					
REMARKS.					PRODUCTION CASING ONLY- N
	SURFACE CASING		,		
		·			
By DON L.	HANOSH	Witness			
	NG MEMBER	10 10			
(Positi	on)				