

Submit 3 Copies To Appropriate District Office
District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Ave., Artesia, NM 88210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources
OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-103
March 4, 2004

WELL API NO. 30-039-30085	
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>	
6. State Oil & Gas Lease No. E-347-27	
7. Lease Name or Unit Agreement Name San Juan 31-6 Unit	
8. Well Number #42Y	
9. OGRID Number 217817	
10. Pool name or Wildcat Blanco Mesaverde / Basin Dakota	
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: Oil Well <input type="checkbox"/> Gas Well <input checked="" type="checkbox"/> Other <input type="checkbox"/>	
2. Name of Operator ConocoPhillips Company	
3. Address of Operator P.O. Box 4289, Farmington, NM 87499-4289	
4. Well Location Unit Letter <u>D</u> : <u>1285</u> feet from the <u>North</u> line and <u>570</u> feet from the <u>West</u> line Section <u>36</u> Township <u>31N</u> Range <u>R6W</u> NMPM Rio Arriba County	
11. Elevation (Show whether DR, RKB, RT, GR, etc. 6441' GL	

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐ MULTIPLE COMPLETION ☐
OTHER ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☒
CASING TEST AND CEMENT JOB ☐
OTHER ☐ spud & plugged report ☒

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

9/25/066 MIRU Mote. Spud 12-1/4" hole @ 0800 hrs 9/25/06. Drilled to 245' Circ. Hole. Surveyed hole and it had deviated 6 degrees. Pumped 4.5 yds (19.2 bbl slurry) 76.5 sx of Type I-II cement w/20% flyash into hole filling hole to surface with cement.

NOTE: This is the well that Mote moved over and tried to re-spud (to replace SJ 31-6 #42F). See spud report for SJ 31-6 #42F. It also deviated 6 degrees and was plugged back. Mote will not be drilling this well in the future. A full size rig will spud and drill this well in the original location. Once this well is properly spud and drilled, reports will be submitted.

I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below-grade tank has been/will be constructed or closed according to NMOCD guidelines ☐, a general permit ☐ or an (attached) alternative OCD-approved plan ☐.

SIGNATURE Patsy Clugston TITLE Sr. Regulatory Specialist DATE 11/13/06

Type or print name Patsy Clugston E-mail address: pclugston@br-inc.com Telephone No. 505-326-9518

(This space for State use)

APPROVED BY H. Villanueva TITLE Deputy Oil & Gas Inspector, District #3 DATE 1-3-08

Conditions of approval, if any:

42Y must have P/A Marker 8/24/08