

Deviation Report

Name of Company
D. J. Simmons, Inc.

Address
1009 Ridgeway Place, Suite 200
Farmington, New Mexico 87401

Lease Name and No.	API Number	Location (Ftg)	Sec, Twn-Rng
Blanco Wash 27 #1	30-045-34096	890'FNL, 450'FEL	Section 27, T-24-N, R-8-W

Pool and Formation	County	State
Lybrook Gallup	San Juan	New Mexico

Survey Depth (ft)	Deviation (degrees)
193'	1.00
401'	1.00
520'	3.75
710'	3.00
890'	2.50
1011'	2.50
1140'	2.75
1284'	2.00
1435'	1.75
1640'	1.50
1885'	1.75
2040'	1.50
2240'	1.75
2454'	1.00
2671'	0.75
2950'	1.00
3263'	0.50
3579'	0.50
3860'	0.50
4155'	0.50
4454'	0.50
4807'	0.50
5080'	0.50

Air Hammer Used? Yes ☒ No

I, the undersigned, certify that I, acting in my capacity as Petroleum Engineer for D. J. Simmons, Inc., am authorized by said Company to make this report; and that this report was prepared under my supervision and directions, and the facts stated herein are true and to the best of my knowledge and belief.

Rodney Z. Seale
Project Engineer
January 30, 2008

Subscribed and sworn to before me on January 30, 2008

Nancy Olthmann
Notary Public in and for San Juan County, New Mexico
My Commission expires on September 22, 2008 ,