



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnrd.state.nm.us/ocd/District III/3distric.htm](http://emnrd.state.nm.us/ocd/District%20III/3district.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 2-1-08 Operator Daguerre Corp API #30-0 45-33-828
Property Name West Bisti 501 Well No. 1 Location: Unit 9 Section 35 Township 26 Range 13
Well Status (Shut-In or Producing) Initial PSI: Tubing 60 Intermediate N/A Casing 0 Bradenhead 30

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing TIME	PRESSURE				
	Bradenhead		INTERM		
	BH	Int	Csg	Int	Csg
5 min					0
10 min					0
15 min					0
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	✓
Nothing	
Gas	RCVD FEB 1 '08
Gas & Water	OIL CONS. DIV.
Water	DIST. 3

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0 INTERMEDIATE N/A

REMARKS: down to nothing in 8 seconds through
1/4" valve.

By Doug Andrusa
(Position)

Witness Monica Luchinger

E-mail address _____