



NEW MEXICO ENERGY, MINERALS
and
NATURAL RESOURCES
DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178
FAX: (505) 334-6170
www.emnrd.state.nm.us/ocd/District 3/district3.htm

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test 2/7/08 Operator: Elm Ridge Exploration CO LLC API #30-039- 20011

Property Name Circo Diablos PC Well No. 5 Location: Unit L Section 10 Township 23 Range 04

Well Status (Shut-In or Producing) Tubing 38 Intermediate 0 Casing 38 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

| TIME | PRESSURES: | | | BRADENHEAD FLOWED | INTERMEDIATE FLOWED |
|------------|------------|--------------|--------|----------------------|------------------------|
| | BRADENHEAD | INTERMEDIATE | CASING | | |
| 5 minutes | | | | Steady Flow | |
| 10 minutes | | | | Surges | |
| 15 minutes | | | | Down to Nothing | |
| 20 minutes | | | | Nothing | |
| 25 minutes | | | | Gas | |
| 30 minutes | | | | Gas & Water | |
| | | | | Water | |

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN BRADENHEAD 0 INTERMEDIATE NA

REMARKS:

Nothing on BRADENHEAD!



By [Signature]

Witness _____

Pumper
(Position)

E-mail address _____